

Technical reports

Last updated: 10 April 2017

Technical reports relating building matters can be viewed in publications and research on the MBIE Corporate website.

For B Stability, technical reports issued by MBIE include:

Investigation into the performance of Statistics House in the 14 November 2016 Kaikōura earthquake

Read the report (<https://www.mbie.govt.nz/building-and-energy/building/investigations-and-reviews-for-safer-buildings/statistics-house-investigation/2017-statistics-house-investigation-report/>)

Dunedin balcony collapse – final report

Read the report (<https://www.mbie.govt.nz/dmsdocument/103-dunedin-balcony-failure-final-report-19-august-2016-pdf>)

Stadium Southland roof collapse report

Read the report (<https://www.mbie.govt.nz/dmsdocument/100-southland-stadium-technical-investigation-pdf>)

Snow storm data collection: Mobilisation in September 2010

Read the report (<https://www.mbie.govt.nz/dmsdocument/69-niwa-snow-storm-data-collection-mobilisation-sept2010-pdf>)

Scion research reports on remedial treatments for timber in leaky buildings

Read the report (<https://www.mbie.govt.nz/dmsdocument/70-niwa-snow-storm-data-collection-mobilisation-sept2010-pdf>)

Review of design and construction of slender precast concrete walls

Read the report (<https://www.mbie.govt.nz/dmsdocument/68-concrete-walls-report-pdf>)



New Zealand Government

This information is published by the Ministry of Business, Innovation and Employment's Chief Executive. It is a general guide only and, if used, does not relieve any person of the obligation to consider any matter to which the information relates according to the circumstances of the particular case. Expert advice may be required in specific circumstances. Where this information relates to assisting people:

- with compliance with the Building Act, it is published under section 175 of the Building Act
- with a Weathertight Services claim, it is published under section 12 of the Weathertight Homes Resolution Services Act 2006.