BUILDING PERFORMANCE

2017/051: Refusal to issue a code compliance certificate for a 10-year-old house with brick veneer cladding

Document

Determination 2017/051

(https://www.building.govt.nz/assets/Uploads/resolving-problems/determinations/2017/2017-051.pdf)

About this determination

Date issued 7 July 2017

E2 - External Moisture (https://www.building.govt.nz/building-code-compliance/e-moisture/e2-external-Primary Building Code clause: moisture/)

Also related to: B1 - Structure (https://www.building.govt.nz/building-code-compliance/b-stability/b1-structure/)

G3 - Food preparation and prevention of contamination (https://www.building.govt.nz/building-code-compliance/g-services-and-facilities/g3-food-preparation-and-prevention-of-contamination/)

G13 - Foul water_(https://www.building.govt.nz/building-code-compliance/g-services-and-facilities/g13-foulwater/)

B2 - Durability (https://www.building.govt.nz/building-code-compliance/b-stability/b2-durability/)

Compliance (https://www.building.govt.nz/resolving-problems/resolution-options/determinations/determinations-issued/?keyword=&topic=Compliance&action_doSearch=Search#results#)

Council: Selwyn District Council

Summary

Primary topic:

This determinatin considers the compliance of the building work, and whether there were reasonable grounds for the authority to issue a code compliance certificate. The determination also discussed inspections undertaken by the authority as a means of providing reasonable grounds on which to issue a code compliance certificate.

Back to determinations register (https://www.building.govt.nz/resolving-problems/resolution-options/determinations/determinations-issued/)



New Zealand Government